Fw: Public Notice of Pollution - Initial Notice Received

- From: Paul Still (stillpe@aol.com)
- To: shannon.n.taylor@floridadep.gov
- Date: Monday, July 29, 2024 at 08:36 PM EDT

Is DEP going to require Radium sampling?

Paul Still

----- Forwarded Message -----From: "no-reply@dep.state.fl.us" <no-reply@dep.state.fl.us> To: "stillpe@aol.com" <stillpe@aol.com> Sent: Monday, July 29, 2024 at 08:28:27 PM EDT Subject: Public Notice of Pollution - Initial Notice Received

DEPARTMA	FLORIDA DEPARTMENT OF	Ron DeSantis
	Environmental Protection	Governor
THENTAL PROTECT	Marjory Stoneman Douglas Building 3900 Commonwealth Boulevard Tallahassee, Florida 32399-3000	Jeanette Nuñez Lt. Governor
		Shawn Hamilton
		Secretary
Pollution Notice		
Pursuant to Section 403.077, F.S., the Department of Environmental Protection has received the following Public Notice of Pollution for a reportable release. All information displayed was submitted by the reporting party.		
Type of Notice: Initial Report Date of Notice: 07/29/2024		
Incident Information Name of Incident: Trail Ridge South Mine - Upset - Pump Malfunction State Watch Office Case Number: 20246237 Start of Incident: 07/29/2024 10:30 AM		

End of Incident: 07/29/2024 10:30 AM

Incident Description

We would like to report an ?upset? condition at the Trail Ridge South Mine. A discharge end of a pipe blew off of a pump. This pump is located at the process pond and adjacent to the industrial waste water ponds. The pipe/line is on the back (discharge) side of the pump. Water flowed to two areas, one being previously mined upland with sand tailings. This area was within our permit limits. The second flow path was into Industrial wastewater pond 1. Water then flowed into IWW pond 2 and 3 at which went out the D001 outfall. This outfall goes into a man made ditch (surface water) from the historic mining operations. This portion of the surface water is permitted for impacts through Permit MMR 137482-018. We continue to work on specific duration and quantity of release. Release was identified at 19:30 am and stopped immediately. Estimated quantity released from D001 is around 30,000 gallons. Water was captured in the 3 IWW ponds and remains site. The following samples for turbidity samples were taken. Process Pond 9.7. D001 Outfall 8.0 Receiving water 7.9 TRS WQ Sampling station BG1 (ERP Permit) ? 9.7

Incident Location

Facility/Installation Name: Trail Rdige South Mine Address Line 1: 5222 Treat Road Address Line 2: Directions: City: Starke FL State: FL Zip Code: 32091 Coordinates (in decimal degrees): Lat: 29.898, Long: -82.041 Click to view Incident Location

Impacted Counties: Clay Updated Impact:

Incident Reported By

Name: Connie Henderson Title: Environmental Manager Phone: (904) 263-8592 Ext: E-mail Address: connie.henderson@chemours.com Relationship: Environmental Manager

On-Site Contact

Name: Connie Henderson Phone: (904) 263-8592 Ext: E-mail Address: connie.henderson@chemours.com

To view a list of all received Public Notices of Pollution or to modify your e-mail subscription settings, please click the link below: <u>Public Notice of Pollution</u>

Florida Department of Environmental Protection

